


#3

FIG. 1



105040-266160

T05040" / E6TE / 60



FIG. 2






FIG. 3




FIG. 4








FIG. 5



TECHNICAL REFERENCE

FIG. 6





TOP SECRET

FIG. 7








FIG. 8



A, B, C ARE HUBS ATTACHED TO SUBNET 15.2.3
X IS NOT A HUB AND IS ON 15.2.3
D IS A HUB BUT IS NOT ATTACHED TO 15.2.3


FIG. 9



A, B, C ARE HUBS ATTACHED TO SUBNET 15.2.3
X IS NOT A HUB AND IS ON 15.2.3
D IS A HUB BUT IS NOT ATTACHED TO 15.2.3

09731937 04501
105040" / FEB 76

FIG. 10



A, B, C ARE HUBS ATTACHED TO SUBNET 15.2.3
X IS NOT A HUB AND IS ON 15.2.3
D IS A HUB BUT IS NOT ATTACHED TO 15.2.3

FIG. 11

